

# ENVIRONMENTAL MONITORING REPORT

September 2022



## ADDRESS

112 Long Point Rd West,  
Warkworth, Singleton  
NSW 2330

# CONTENTS

1.	Site Details	3
2.	Air Quality Monitoring	3
3.	Water Monitoring	3
I.	HRSTS Discharge Volume and Quality	
II.	Discharge Quality	



## 1. SITE DETAILS

### LICENSE HOLDER

Verdant Earth Technologies

### EPL NUMBER

11262 ([link](#))



## 2. AIR QUALITY MONITORING

Given that the plant was not operational during the reporting period, no air quality monitoring was undertaken.

## 3. WATER MONITORING

### I. HRSTS Discharge Volume and Quality

No water was discharged under the HRSTS during the reporting period.

### II. Discharge Quality

No water was discharged from site during the reporting period.

